

HK QGS LIMITED Final Random Inspection Report

Client Ref. No.: 2250 | Report No.: 2250001 | Date: July 13th ,2022 | Total page: 13

GENERAL SUMMAI	GENERAL SUMMARY:					
Client:	Hayri GENC					
Product Description:	Second-hand excavator					
Supplier:	Shanghai Shenhu Packaging					
Supplier.	Machinery Equipment Co., Ltd.					
Contact person:	Leon					
Insp. Location:	Shanghai					
Inspector:	Parker					
Date of insp.:	July 13 th , 2022					



AVAILABLE QUANTITY:							
Order No.	Item	Order Qty	Packed	Not packed	Not finished	Inspect Qty	
-	Second-hand excavator	1	0	1	0	1	

Inspection standard: ANSI/ASQC Z1.4-2003		Sample Size: 1 pc				
		Critical	Major	Minor		
Sampling plan: Single, Normal Inspection level: AQL: Critical: Not Allowed.	AQL:	-	-	-		
	Defects Found:	-	1	-		
AGE. Critical. Not Allowed.	Max. Allowed:	-	-	-		

OVERALL CONCLUSION:				
Inspection criteria	Passed	Failed	Pending	Comments
Quantity available:	×	-	-	ОК
Workmanship:	-	-	×	See remark 2/3
Test:	-	-	×	See remark 1
Data measurement:	×	-	-	ОК
Labeling:	-	-	×	See remark 4
Shipping mark:	-	-	×	See remark 4
Result:	[] Accep	table [] Reject	[X] Pending

SPECIAL REMARK:

- 1. Due to space limitation, and factory couldn't get the car out, the functions of this machine cannot be fully demonstrated. Please refer to the actual pictures and test videos.
- 2. The appearance of the product and the cab should be based on the video and photo.
- 3. Right side lamp at front middle arm was missing.
- 4. The factory said that the equipment (nameplate * CAT0320DHJFZ07134 *) required by the customer cannot work .The supplier had changed another machine for our inspection on site . The nameplate No of this machine is * CAT0320DLPCM02008* . Please refer to the actual nameplate picture .
- 5. The actual working hours is 1618 hours, please refer to the actual picture for the working time of the equipment.



HK QGS LIMITED Final Random Inspection Report

Client Ref. No.: 2250 Report No.: 2250001 Date: July 13th ,2022 Total page: 13

6. Only the light in tool box can functioned, the others lights can not funtioned. The supplier said the cable was broken and they will repair it .

WORKMANS	HIP:			
Item .	Defects Description	Cri	Maj	Min
Second-hand excavator	Right side lamp at front middle arm was missing .	-	-	-
	Defects found:	-	1	-
	Max allow:	-	-	-
	Result:	Pendi	ng for re	emark

TEST AND MEASUREMENT:						
Test items	Sample size	Passed	Failed	Pending	Comments	
Function test:	1pcs/item	-	-	X	See remark 1, 5	

PACKING AND ACCESSORIES:						
Item No.:	Master shipper (pcs/ctn)	Carton size L×W×H (cm)	G.W (Kgs)	N.W (Kgs)	Carton Barcode	Product Barcode
-	-	-	-	-	-	-

EXPORT CARTON INFORMATION:							
Carton:	New export carton	-	0	Opaque gummed tape	-		
Fastening:	Metal staples	-	Sealing:	Transparent gummed tape	-		
Strapping:	Nylonx4	-		Paper tape	-		
Material:	Ply of corrugated paper	-	Others:	-			

PRODUCT AND DEFECTS PHOTO SHOW:





Machine view(Right side lamp missing)

This report only reflects the truth of quality in this lots goods, based on statistical sampling procedure. Inspection is performed to the best of our ability and skills but without responsibility on our part, nor does it evidence shipment. Our Website: www.qgs.com.cn



HK QGS LIMITED Final Random Inspection Report

Client Ref. No.: 2250 | Report No.: 2250001 | Date: July 13th ,2022 | Total page: 13

(SN serial number:*CAT0320DLPCM02008*)





Machine view



Machine view



Machine view



Machine view



Internal checking

Internal checking



HK QGS LIMITED **Final Random Inspection Report**

Date: July 13th ,2022 Client Ref. No.: 2250 Report No.: 2250001 Total page: 13





Machine view

Machine view





Machine view

Machine view



Control room

Control room



HK QGS LIMITED Final Random Inspection Report

Client Ref. No.: 2250 Date: July 13th ,2022 Report No.: 2250001 Total page: 13 366-0367 **Control room** Hours **Control room Control room Control room Control room**



HK QGS LIMITED Final Random Inspection Report

Client Ref. No.: 2250 Report No.: 2250001 Date: July 13th ,2022 Total page: 13





Control room



Hydraulic system



Hydraulic system



Internal checking



Hydraulic system

Hydraulic system



HK QGS LIMITED Final Random Inspection Report

Client Ref. No.: 2250 | Report No.: 2250001 | Date: July 13th ,2022 | Total page: 13



Hydraulic system

Hydraulic system





Hydraulic system

Hydraulic system





Hydraulic system

Hydraulic system



HK QGS LIMITED Final Random Inspection Report

Client Ref. No.: 2250 | Report No.: 2250001 | Date: July 13th, 2022 | Total page: 13





Internal view

view Internal view





Internal view

Internal view





Internal view

Internal view



HK QGS LIMITED Final Random Inspection Report

Quality Assure In China Date: July 13th ,2022 Client Ref. No.: 2250 Report No.: 2250001 Total page: 13 Internal view **Machine view** Internal view Internal view

Internal view

Internal view



HK QGS LIMITED **Final Random Inspection Report**

Date: July 13th ,2022 Client Ref. No.: 2250 Report No.: 2250001 Total page: 13





Internal view



Internal view



Internal view



Internal view



Internal view

Internal view



HK QGS LIMITED Final Random Inspection Report

Quality Assure In China Date: July 13th ,2022 Client Ref. No.: 2250 Report No.: 2250001 Total page: 13 Internal view **Machine view** Machine view Internal checking

Hydraulic system

Internal checking



HK QGS LIMITED Final Random Inspection Report

Client Ref. No.: 2250 Report No.: 2250001 Date: July 13th, 2022 Total page: 13





Internal checking



Internal checking



Internal checking

Internal checking **Factory view**



Factory gate



business license



HK QGS LIMITED Final Random Inspection Report

Client Ref. No.: 2250 Report No.: 2250001 Date: July 13th ,2022 Total page: 13





The office view

The factory view

END